# Quick Start Guide 4850PDR

Optically Isolated RS-422/485 Repeater



## 1

## Check for All Required Hardware

- 485OPDR Optically Isolated Repeater
- ☐ This Quick Start Guide
- □ Additional Items Required but not included
  - Power Supply (10 to 30 VDC, 0.7 W)
  - o RS-422/485 Cable.

# 2

## **UL Installation Information**

Underwriters Laboratories Conditions of Acceptability – When installed in the end-use equipment, consideration should be given to the following:

- 1. The wiring terminals are suitable for factory wiring only.
- 2. This device is to be mounted in a suitable enclosure in the end-product.
- This device is suitable for operation at a maximum surrounding air temperature as described in the documentation.
- These devices are intended for use in a pollution degree 2 environment.


Input Voltage: 10 – 30 VDC
Input Power: 0.7 Watts
Wire Range: 12 – 24 AWG

Tightening Torque: 4 kgf-cm

- Temperature rating of field installed conductors is 105 C minimum, sized for 60 C ampacity.
- Use copper wire only
- Maximum surrounding ambient air temperature 80 C.



## **Information – Connectors**



Terminal Block	Signal	
Α	OUT (+)	
В	IN (+)	-
С	PROTECTED GROUND	SOL
D	OUT (-)	Isolated
E	IN (-)	0
F	SIGNAL GROUND	
G	IN (-)	z
Н	OUT (-)	Non-Isolated
J	+10 TO 30 VDC	·lso
K	IN (+)	lat
L	OUT (+)	be
М	GROUND	

Bias is provided by  $4.7k\Omega$  pull-up/down resistors on the data in lines. This value is adequate for most application without termination. If another value is required, space is provided on the PCP for through hole resistor placement (R12, R21, R14, and R23)



## **Information - DIP Switch**

### **Communications Mode**

	SW-7	SW-8
	TX Enable	RX Enable
RS-485		
2-Wire	ON	ON
Half Duplex		
RS-485		
4-Wire	ON	OFF
Full Duplex		
RS-422	OFF	OFF
Full Duplex	OFF	UFF

Consider la

### **Timeout Selection**

	Switch							
K baud	1	2	3	4	5	6	Timeout (ms)	
1.2 #	OFF	OFF	OFF	OFF	OFF	OFF	9.02	
2.4	ON	OFF	OFF	OFF	OFF	OFF	4.73	1
4.8	OFF	ON	OFF	OFF	OFF	OFF	2.20	1
9.6	OFF	OFF	ON	OFF	OFF	OFF	1.10	1
19.2	OFF	OFF	OFF	ON	OFF	OFF	0.62	1
38.4	OFF	OFF	OFF	OFF	ON	OFF	0.29	1
57.6	OFF	OFF	OFF	OFF	OFF	ON	0.17	1
76.8	OFF	OFF	OFF	ON	OFF	ON	0.15	1
115.2	OFF	OFF	OFF	ON	ON	ON	0.11	1
153.6 #	OFF	OFF	OFF	OFF	OFF	OFF	0.07	1
230.4 #	OFF	OFF	OFF	OFF	OFF	OFF	0.05	
460.8 #	OFF	OFF	OFF	OFF	OFF	OFF	0.02	

Timeout selections are equal to one character time at the indicated baud rate. Setting the converter 9600 will generally work at 9600 and higher baud rates. In RS-422 mode, timeouts are not required.

# To achieve these timeouts you must place a through -hole resistor on the circuit board. See Step 5 for more information.




## Through-hole resistor placement (Optional)

If you need to support timeouts indicated with a # in Step 4, you must place through-hole resistors on the PCB. Place the resistor in the R-7 and R-28 spot designated on the board. Switches 1 through 6 must be turned OFF.

### **Through-hole Resistor Values**

K Baud	Timeout (MS)	R-7 / R-28 Value
1.2	9.02	820 k Ω
153.6	0.07	6.2 k Ω
230.4	0.05	4.3 k Ω
460.8	0.02	2 k Ω


## **Power Connection**




Isolated Repeater uses 0.7 W


## Wiring Examples


## RS-422 / 4-Wire RS-485





## 2-Wire RS-485







International Office: 707 Dayton Road - PO Box 1040 - Ottawa, IL 61350 USA 815.433.5100 Fax 815.433.5104 orders@bb-elec.com support@bb-elec.com